



LEVIOR s.r.o

NÁVOD K POUŽITÍ CZ / USERS MANUAL ENG

Obecné pokyny:

Podnikatelé jsou povinni výrobek provozovat ve smyslu Nařízení vlády NV192/2022 a ČSN 690012.

Při použití používejte ochranný oděv. Udržujte pracovní prostor čistý a vždy budte ve stabilní poloze. Nedovolte, aby nezkušené osoby používaly přístroj. Udržujte děti a zvířata v dostatečné vzdálenosti od pracovního prostoru. Nesprávné použití stlačeného vzduchu může způsobit vážná zranění.

1) Pistole foukací s manometrem:

Technické údaje: Maximální tlak: 12 bar.

Návod k použití: Připojte vzduchovou hadici k tělu pistole (1). K Nahustění pneumatiky zkontrolujte tlak, vložte spojku (2) k ventilu pneumatiky podržte spoušť (4). S budíkem nasměřovaným čelem k Vám sledujte tlak. Při nedostatečné hodnotě tlaku na budíku zmáčkněte spoušť na několik sekund a poté ji uvolněte, opakujte tento postup dokud nezískáte požadovaný tlak. Pro deflaci, uvolněte páčku (4) a stiskněte palce tlačítko (5) dokud všechny přebytečný vzduch nebude vyloučen. (C-D)

Upozornění: Nikdy nepřekračujte tlak huštění doporučený v návodu. Chraňte měřidlo proti nárazům. V případě dopadů, proveďte kalibraci.

2) Ofukovací pistole:

Technické údaje: Doporučený provozní tlak: 4/5 bar

Návod k použití: Pistole s horním zásobníkem (4.1): Našroubujte nádobu (1) do těla pistole (3). Naplňte miskou s barvou (1) a uzavřete ji víkem (4). Ujistěte se, že odvětrávací ventil (5) je otevřený. Pistole s dolním zásobníkem (4.2): Našroubujte nádobu (10) do těla pistole (3) a zajistěte pevně klíčem. Naplňte nádobu (11) barvou a uzavřete ji víkem (10) upevněte otočením čtvrt otáčky doprava.

Napojte hadici na tělo pistole(6) a nastavte tlak (4/5 bar) u kompresoru. Použijte zadní kroužek matice (7) pro nastavení množství barvy (utáhněte pokud používáte více tekuté barvy, otevřete v případě hsuší barvy) a matici (8) pužijte k regulaci proudu trysky. (E-F / G-H). Pře použitím vyzkoušejte pistolí na zkušebním materiálu dokud nezískáte optimální nastavení a efekt. Nikdy nenechávejte barvu uvnitř mísy, může to způsobit nenapravitelné škody. Po použití vždy vyčistěte naplněním nádoby čistým rozpouštědlem a stříkáním na povrch tak aby nedošlo ke znečištění okolního prostředí (stříkejte na pohlcující povrch), dokud není ani stopa po barvě. Vyčistěte vnější části pistole od barvy použitím hadru namočeného v rozpouštědle. Pro více důkladné čištění, kompletně ošroubujte zadní kruhovou matici (7) a dávejte pozor, abyste neztratili vnitřní pružinu, vytáhněte jehlu z trysky, povolte přední kroužek (9), vyjměte děrovanou hlavu trysky (2) a vyšroubujte trysku a dejte všechny komponenty v nádobu s čistým rozpouštědlem pár hodin, osušte komponenty pečlivě a poté provedtě výše uvedený postup v obráceném pořadí, aby pistol složili.

Upozornění: Nepoužívejte pistol v uzavřeném prostředí bez větrání. Nepoužívejte aniž byste používali respirační masku.

3) Spirálová hadice s rychlospojku:

Technické údaje: Maximální tlak: 12bar

Návod na použití kabelu s rychlospojku: Připojte konec kabelu vybaveného konektorem (1) do kompresoru, připojte konec vybavené konektorem (2) do k přístroji. Připojení konektoru (2) musí zaklapnout.

Chcete-li odpojit kabel, jednou rukou přidržte koncovku kompresoru a druhou rukou odpojte hadici (2) s druhou a táhněte v opačném směru. Pokud jde tato operace ztěžka ujistěte se, že jste vypustil všechny vzduch z kabelu. (I-L)

Instrukce pro použití kabelu s bajonetový uzávěr: Pro připojení kabelu k nástroji, přiložte koncovku (2) k nástroji a pevně ji utahněte.

Chcete-li odpojit kabel do povolte matici a vysuňte šroubení, pokud je tato operace je obtížná, ujistěte se, že zou byl vypuštěn všechny vzduch z kabelu. (M-N)

Upozornění: Před připojením nebo odpojením kabelu se ujistěte, že jste vypnut kompresor. Kabel se násilně ohýbat.

General Warnings:

Businessmen are obliged to operate the product in accordance with Government Regulation NV192/2022 and ČSN 690012.

When using air-powered accessories, always wear safety clothes. Keep the work area free and always maintain in a stable position. Do not allow inexpert persons to use tools without suitable supervision. Keep children and animals at a distance from the work area.

Improper use of compressed air may cause serious injuries.

1) Inflation Gun with manometer:

Technical data: Maximal pressure:12 bar.

Instruction for use: Connect the air hose to the inlet fitting (1) on the gun. To inflate the tire and check the pressure, insert the fitting (2) in the valve of the tire holding down the lever (3) on this; following insertion, release the lever (3). With the gauge facing you, read the pressure; for inflation, press the lever (4) fully for few seconds and then release it; repeat the operation until you have obtained the pressure required as shown by the needle on the dial of the gauge. For deflation, release the lever (4) and press the button (5) with your thumb until all the air has been expelled. (C-D) **Warning:** Never exceed the inflation pressure recommended in the instruction for use of the object to be inflated. Protect the gauge against impacts. In the case of impacts, check calibration.

2) Blowing Gun:

Technical data: Recommended operating pressure: 4/5 bar

Instruction for use: Airbrush with gravity bowl (4.1): Screw the bowl (1) to the body of the gun (3). Fill the bowl with paint (1) and close it with the lid (4). Make sure that the vent valve (5) is open. Airbrush with low bowl (4.2): Screw the bowl (10) to the body of the gun (3) and secure tightly with a wrench. Fill the bowl (11) with paint and fit it on the cover (10); fasten with a quarter turn to the right.

Connect the air hose to the inlet fitting (6) on the gun and adjust the pressure (4/5 bar) from the compressor. Use the rear ring-nut (7) to adjust the amount of paint to be sprayed (tighten if you are using more fluid paints, open in the case of thicker paints) and the side ring-nut (8) to regulate the size of the jet. (E-F /G-H). Direct the front perforated head of the nozzle (2) so that it is perpendicular to the direction of the painting. Prior to effective use, practise on a test material until you have obtained optimal adjustment and effect. Never leave paint inside the bowl in order to use this subsequently as this may cause irreparable damage to the precision parts of the air brush. After use, always clean the inside the air brush thoroughly, filling the bowl with pure solvent and spraying this without polluting the environment (spray on a rag or absorbing surface) until there is no trace of the paint used in the jet of the solvent sprayed. Clean the external parts of the gun stained by the paint used with a rag dipped in solvent. For more thorough cleaning, completely unscrew the rear ring-nut (7) and, taking care not to lose the internal spring, remove the needle of the nozzle; then loosen the front ring (9) and remove the perforated head of the nozzle (2) and unscrew the nozzle with a wrench; put all the components in a container with pure solvent for number of hours; dry the components carefully and then carry out the above procedure in reverse order in order to re-assemble all the parts.

Warning: Do not use the paint gun in a closed environment without ventilation. Do not use the air brush without wearing a safety mask.

3) Spiral Cord:

Technical data: Max pressure: 12bar

Instructions for use of cord with fast disconnects: Connect the end of the cord fitted with connector (1) to the compressor; connect the other end fitted with connector (2) to the air powered tool. To insert the connector (2) in the tool, push until it clicks in place. To detach the cord, grasp the tool firmly with one hand and the ring-nut of the connector (2) with the other and pull in the opposite direction. If this operation is difficult, make sure that you have vented all the air from the cord. (I-L)

Instructions for use of cord with bayonet fitting: To connect the cord to the tool, insert the fitting of the cord (2) in the ring-nut on the tool and draw up tightly. To detach the cord, loosen the ring-nut on the tool and slide out the fitting; if this operation is difficult, make sure that you have vented all the air from the cord. (M-N) **Warning:** Before connecting or disconnecting a tool of the cord, make sure that you have switched off the compressor. The cord must not be crushed or bent as it could be pierced.

